



# MICROCHIP PIC18F2220/2320/4220/4320

## PIC18F2220/2320/4220/4320 Rev. C1 Silicon Errata

The PIC18F2220/2320/4220/4320 Rev. C1 parts you have received conform functionally to the Device Data Sheet (DS39599G), except for the anomalies described below. Any Data Sheet Clarification issues related to the PIC18F2220/2320/4220/4320 will be reported in a separate Data Sheet errata. Please check the Microchip web site for any existing issues.

The following silicon errata apply only to PIC18F2220/2320/4220/4320 devices with these Device/Revision IDs:

| Part Number | Device ID     | Revision ID |
|-------------|---------------|-------------|
| PIC18F2220  | 0000 0101 100 | 0 0110      |
| PIC18F2320  | 0000 0101 000 | 0 0110      |
| PIC18F4220  | 0000 0101 101 | 0 0110      |
| PIC18F4320  | 0000 0101 001 | 0 0110      |

The Device IDs (DEVID1 and DEVID2) are located at addresses 3FFFFEh:3FFFFFh in the device's configuration space. They are shown in binary in the format "DEVID2 DEVID1".

All of the issues listed here will be addressed in future revisions of the PIC18F2220/2320/4220/4320 silicon.

### 1. Module: Core (DAW Instruction)

The DAW instruction may improperly clear the Carry bit (STATUS<0>) when executed.

#### Work around

Test the Carry bit state before executing the DAW instruction. If the Carry bit is set, increment the next higher byte to be added, using an instruction such as INCF SZ (this instruction does not affect any Status flags and will not overflow a BCD nibble). After the DAW instruction has been executed, process the Carry bit normally (see Example 1).

#### EXAMPLE 1: PROCESSING THE CARRY BIT DURING BCD ADDITIONS

```

MOVLW 0x80      ; .80 (BCD)
ADDLW 0x80      ; .80 (BCD)

BTFSC STATUS, C ; test C
INCF SZ byte2   ; inc next higher LSB
DAW
BTFSC STATUS, C ; test C
INCF SZ byte2   ; inc next higher LSB

This is repeated for each DAW instruction.

```

#### Date Codes that pertain to this issue:

All engineering and production devices.

# PIC18F2220/2320/4220/4320

---

## 2. Module: MSSP (All I<sup>2</sup>C™ and SPI Modes)

The Buffer Full flag bit (BF) of the SSPSTAT register (SSPSTAT<0>) may be inadvertently cleared, even when the SSPBUF register has not been read. This will occur only when the following two conditions occur simultaneously:

- The four Least Significant bits of the BSR register are equal to 0Fh (BSR<3:0> = 1111) and
- Any instruction that contains C9h in its 8 Least Significant bits (i.e., register file addresses, literal data, address offsets, etc.) is executed.

### **Work around**

Identified work arounds will involve setting the contents of BSR<3:0> to some value other than 0Fh.

In addition to those proposed below, other solutions may exist.

1. When developing or modifying code, keep these guidelines in mind:
  - Assign 12-bit addresses to all variables. This allows the assembler to know when Access Banking can be used.
  - Do not set the BSR to point to Bank 15 (BSR = 0Fh).
  - Allow the assembler to manipulate the Access bit present in most instructions. Accessing the SFRs in Bank 15 will be done through the Access Bank. Continue to use the BSR to select all GPR Banks.
2. If accessing a part of Bank 15 is required and the use of Access Banking is not possible, consider using indirect addressing.
3. If pointing the BSR to Bank 15 is unavoidable, review the absolute file listing. Verify that no instructions contain C9h in the 8 Least Significant bits while the BSR points to Bank 15 (BSR = 0Fh).

### **Date Codes that pertain to this issue:**

All engineering and production devices.

## 3. Module: MSSP (SPI, Slave Mode)

In its current implementation, the  $\overline{SS}$  (Slave Select) control signal generated by an external master processor may not be successfully recognized by the PIC® microcontroller operating in Slave Select mode (SSPM3:SSPM0 = 0100). In particular, it has been observed that faster transitions (those with shorter fall times) are more likely to be missed than slower transitions.

### **Work around**

Insert a series resistor between the source of the  $\overline{SS}$  signal and the corresponding  $\overline{SS}$  input line of the microcontroller. The value of the resistor is dependent on both the application system's characteristics and process variations between microcontrollers. Experimentation and thorough testing is encouraged.

This is a recommended solution; others may exist.

### **Date Codes that pertain to this issue:**

All engineering and production devices.

## 4. Module: Oscillator

The 32 kHz internal oscillator, INTRC, will be held in Reset if either of the following is enabled:

- Power-up Timer
- High-Speed Crystal/Resonator with PLL Enabled (HSPLL) Oscillator mode

Without the INTRC oscillator running, the Power-up Timer and Phase Locked Loop (PLL) timer will not expire and the PIC18F2220/2320/4220/4320 device will not exit Reset. This issue does not affect the Watchdog Timer or any other mode.

The provided work arounds require only two modifications to the Configuration Word values. No additional changes to the application hardware or software are necessary, except as noted below.

### **Work around: Power-up Timer**

Disable the Power-up Timer by programming PWRTEN (CONFIG2L<0>) to '1'. This results in a shorter time before the microcontroller begins to execute code after power up or exiting from Sleep mode or from Brown-out Reset (if enabled).

If a power-up delay is needed to ensure a stable VDD, consider using the Brown-out Reset (BOR) feature. The BOR keeps the device in Reset until the specified VDD has been achieved.

This work around is available by programming the BOR bit to '1' and selecting BOR voltage bits with BORV<1:0> bits in the CONFIG2L Configuration Word.

If BOR is not enabled and additional start-up delay is needed, consider implementing an external system supervisor to keep the microcontroller in Reset until the VDD has stabilized. Alternately, consider use of an equivalent PIC18F4321 device.

### **Work around: HSPLL Oscillator Mode**

Two work arounds are available through the Configuration bits. Enabling either of the following features permits the HSPLL mode to work successfully:

- Two-Speed Start-up
- Fail-Safe Clock Monitor

Both options permit the microcontroller to start from the 32 kHz INTRC after power-up, BOR, or wake-up from Sleep mode. The options also permit code to execute while PLL is waiting to lock.

The PLL lock time typically is 2 ms which results in approximately 16 instruction executions before the switch to the HSPLL clock occurs. If typical initialization code is performed after a Power-on Reset or Brown-out Reset, the impact of this work around should be negligible.

If Sleep mode is used, both work arounds result in code execution during PLL lock time. A software delay may be needed to avoid executing time-critical code after wake-up. The OSTS (OSCCON<3>) bit will set to indicate when the HSPLL is ready and time-critical code can be executed.

The Two-Speed Start-up and Fail-Safe Clock Monitor work arounds switch the system clock source from INTRC to HSPLL mode after a PLL lock occurs. This is handled automatically by the microcontroller and requires no additional software or special monitoring. For more information, see **Section 2.7 "Clock Sources and Oscillator Switching"** in the *"PIC18F2220/2320/4220/4320 Data Sheet"* (DS39599).

### **Date Codes that pertain to this issue:**

Engineering and production devices with a date code of 0813 or later may be affected.

# PIC18F2220/2320/4220/4320

---

## REVISION HISTORY

### Rev A Document (9/2008)

First revision of this document. Includes silicon issues 1 (Core – DAW Instruction), 2 (MSSP – All I<sup>2</sup>C™ and SPI modes), 3 (MSSP – SPI, Slave Mode) and 4 (INTRC Oscillator).

### Rev B Document (1/2009)

Changed title of silicon issue 4 (Oscillator).

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

**Trademarks**

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, rfPIC, SmartShunt and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, PICkit, PICDEM, PICDEM.net, PICtail, PIC<sup>32</sup> logo, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rLAB, Select Mode, Total Endurance, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2009, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

**QUALITY MANAGEMENT SYSTEM**  
**CERTIFIED BY DNV**  
**== ISO/TS 16949:2002 ==**

*Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



## WORLDWIDE SALES AND SERVICE

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://support.microchip.com>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

**Kokomo**  
Kokomo, IN  
Tel: 765-864-8360  
Fax: 765-864-8387

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**Santa Clara**  
Santa Clara, CA  
Tel: 408-961-6444  
Fax: 408-961-6445

**Toronto**  
Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8528-2100  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Hong Kong SAR**  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**China - Nanjing**  
Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xiamen**  
Tel: 86-592-2388138  
Fax: 86-592-2388130

**China - Xian**  
Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

**China - Zhuhai**  
Tel: 86-756-3210040  
Fax: 86-756-3210049

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444  
Fax: 91-80-3090-4080

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

**Japan - Yokohama**  
Tel: 81-45-471- 6166  
Fax: 81-45-471-6122

**Korea - Daegu**  
Tel: 82-53-744-4301  
Fax: 82-53-744-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Kuala Lumpur**  
Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

**Malaysia - Penang**  
Tel: 60-4-227-8870  
Fax: 60-4-227-4068

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-572-9526  
Fax: 886-3-572-6459

**Taiwan - Kaohsiung**  
Tel: 886-7-536-4818  
Fax: 886-7-536-4803

**Taiwan - Taipei**  
Tel: 886-2-2500-6610  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**UK - Wokingham**  
Tel: 44-118-921-5869  
Fax: 44-118-921-5820